




## How to Recover the Meter from Firmware Update Failure

### Preparation


1. AcuvimII meter to recover
2. AcuvimII meter firmware update software (USProgram)
3. AcuvimII meter firmware (.abin file)
4. RS485 cable

### Procedure


1. Open USProgram.exe. Load firmware file



2. Power on the meter.
3. Click “Request” in the software program, and then select “Send programming command”.



- Click "Download" and wait for the progress to be completed.



Accuenergy Inc.

440 Comstock Rd, Toronto, ON M1L 2H6, Canada

Tel: +1 (416) 497-4100 | Fax: +1 (416) 497-4130

Email: [marketing@accuenergy.com](mailto:marketing@accuenergy.com)

**MAKE ENERGY USAGE SMARTER**